



Photo 1 – Main wreckage at accident site



Photo 2 – Left wing at accident site



Photo 3 – Engine during layout examination



Photo 4 – Airframe during layout examination



Photo 5 – Vacuum pump during layout examination



Photo 6 – Gyroscope housing showing rotational scoring



Photo 7 – Gyroscope core showing rotational scoring