



Photo 1 - Accident Site



Photo 2 - Cabin Area



Photo 3 - Propeller



Photo 4 - Engine



Photo 5 – Attitude Indicator Gyro