



Photo 1 – View of the accident site looking down from a balcony.



Photo 2 - View of a separated section of a wing.



Photo 3 - View of the right side of the inverted, separated empennage.



Photo 4 - View of control cables forward of the empennage.



Photo 5 - View of the engine embedded in terrain and a linear ground scar.



Photo 6 - View of the engine embedded in terrain and a linear ground scar.



Photo 7 - View of a separated main landing gear.



Photo 8 - View of a separated main landing gear.



Photo 9 - Close up view of the embedded engine.



Photo 10 - View of a separated section of a wing spar.



Photo 11 - View of a separated section of a wing spar with the embedded engine in the background.



Photo 12 - View of impacted ground vehicles.



Photo 13 - View of the separated empennage near impacted ground vehicles.



Photo 14 - View of the separated flight control cables.



Photo 15 - View of the recovered, separated propeller blades.



Photo 16 - View of a ground scar near the location of a propeller blade.



Photo 17 - View of the recovered engine and an attached propeller blade.



Photo 18 - Side view of the recovered engine.



Photo 19 - Front view of the recovered engine and an attached propeller blade.



Photo 20 - View of the separated fuel selector valve.