

Hatch Craig

From: Hatch Craig
Sent: Monday, September 16, 2019 9:36 AM
To: [REDACTED]
Subject: RE: Anderson, IN Seneca engine exam.
Attachments: Accident Servo.jpg; Exemplar servo.jpg

Hi

We examined the left engine on the Seneca last week. (just a quick note on a finding),, the engine was too rich,, and really didn't want to run (also note the black condition of the sparkplugs we found on site). The attached photo, (accident servo),, note the "control arm" placement (top right side),, the rod is on the lower side of the shaft. The exemplar photo,, (servo on the engine- again right side of the photo),, the arm is basically on the shaft part and will rotate up (clockwise) on the shaft and will remain on the upper part of the shaft. Somehow the servo was misadjusted.

Craig Hatch

(mailing address only)
4760 Oakland St. Suite 500
Denver, CO 80239

M-F 7:00 to 15:30 Central

[REDACTED]

[REDACTED]