



Photo 1 – Accident Site as Viewed from the Right Wing Tip



Photo 2 – Accident Site as Viewed from the Tail Section



Photo 3 – Airplane Engine After Removal from Embedded Terrain and Airplane Structure