



**Photo 1 – View to the east, showing wreckage and its proximity to runway 9 threshold. (Ohio State Police photo)**



**Photo 2 - Aerial view of wreckage and ground scar. (Ohio State Police photo)**



**Photo 3 - View to the northeast at aircraft wreckage and ground scar. Runway 9 threshold is at right. (Ohio State Police photo)**



**Photo 4 - Ground scar leading to the wreckage. (Textron photo)**



**Photo 5 - Frontal view of aircraft wreckage. (Textron photo)**



**Photo 6 - Left side of airplane. (Textron photo)**



**Photo 7 - The engine. (Textron photo)**



**Photo 8 - Propeller blade A, recovered at crash site. (Textron photo)**



**Photo 9 - Recovered propeller blade B, found by farmer. (FAA photo)**



**Photo 10 - Portion of the instrument panel. (Textron photo)**



**Photo 11 - Airspeed indicator. (Textron photo)**



**Photo 12 - Flap actuator measurement. (Textron photo)**