



Photo 1 – Airplane at Accident Site After Fire was Extinguished (Courtesy of Owner/Operator)

19-24 Nov 2018, Tach Time 994.3, Total Time 1475.3,
Drained oil, removed filter, installed new Champion
48110-1 Filter and 7 qts. Aeroshell 15W50 oil. Replaced all
fuel and oil hoses with new hoses fabricated by Aviall
Hose Shop, KAPA. Cleaned and oiled air filter.
Replaced broken alternator output ring terminal,
fabricated and installed alternator air blast tube. James
Taylor A&P [REDACTED] [REDACTED]

Photo 2 – Maintenance Entry for Replacement of Fuel Hose Lines (Courtesy of Owner/Operator)



Photo 3 – Fuel Line Components collected from Accident Airplane (Courtesy of NTSB)