

## N233P Apache – Aircraft Damages Photo Sheet:

**Aircraft:** 1956 Apache

**File #:** AC-19-10311



**Picture No:** 1

**Description:** Aircraft crashed in a field near Sulphur Springs, TX. 33.1931N 95.6113W



**Picture No:** 2

**Description:** Front right view right wing and right engine is damaged. Aircraft nose wheel has broken free.

## N233P Apache – Aircraft Damages Photo Sheet:

**Aircraft:** 1956 Apache

**File #:** AC-19-10311



**Picture No:** 3

**Description:** Front left view. Pilot windscreen was kicked out by pilot. Visible damage to propeller and engine.



**Picture No:** 4

**Description:** Significant damage to the left engine mount. Propeller blades are bent from contact with ground. Left main mount has collapsed.

## N233P Apache – Aircraft Damages Photo Sheet:

**Aircraft:** 1956 Apache

**File #:** AC-19-10311



**Picture No:** 5

**Description:** Left wing leading edge is destroyed.



**Picture No:** 6

**Description:** View of left side. Wing tip was torn free.

## N233P Apache – Aircraft Damages Photo Sheet:

**Aircraft:** 1956 Apache

**File #:** AC-19-10311



**Picture No:** 7

**Description:** Left flap is bent/damaged.



**Picture No:** 8

**Description:** Left aft view, tail does not appear to have damage.

## N233P Apache – Aircraft Damages Photo Sheet:

**Aircraft:** 1956 Apache

**File #:** AC-19-10311



**Picture No:** 9

**Description:** View of aircraft from rear.



**Picture No:** 10

**Description:** Aircraft right rear quarter. Damage to right wing, right landing gear is torn loose from mount.

## N233P Apache – Aircraft Damages Photo Sheet:

**Aircraft:** 1956 Apache

**File #:** AC-19-10311



**Picture No:** 11

**Description:** Right wing is destroyed. Aileron is torn loose, leading edge is crushed, engine mount is bent down and aft.



**Picture No:** 12

**Description:** Right propeller could be intact as a result of propeller position being perpendicular to the ground when the engine seized.

## N233P Apache – Aircraft Damages Photo Sheet:

**Aircraft:** 1956 Apache

**File #:** AC-19-10311



**Picture No:** 13

**Description:** right front view  
nose structure shows impact  
crush damage.



**Picture No:** 14

**Description:** front right view  
of nose skin and structural  
damage.

## N233P Apache – Aircraft Damages Photo Sheet:

**Aircraft:** 1956 Apache

**File #:** AC-19-10311



**Picture No:** 15

**Description:** front view of aircraft.



**Picture No:** 16

**Description:** Panel left side.

## N233P Apache – Aircraft Damages Photo Sheet:

**Aircraft:** 1956 Apache

**File #:** AC-19-10311



**Picture No:** 17

**Description:** Panel right side.  
Avionics was removed to prevent theft.



**Picture No:** 18

**Description:** Interior view.  
New upholstery.