



SUMMARY OF FAA INSPECTOR'S FINDINGS

Jason Aguilera
Air Safety Investigator
Central Region

In addition to collecting pilot and airplane information, the responding FAA inspector made the following observations:

- Removed the cowlings around the engine and visually inspected the area.
- Oil was observed in the cowling and some oil on the exhaust pipe.
 - o The source could not be determined.
- A borescope was inserted through the engine case breather
 - o Examination of the seal and general engine components were unremarkable.
- The heads of the odd cylinders were removed and examined.
- No discrepancies were noted with the engine.

---END---