



Photo 1 – FAA supplied view of the front of the airplane.



Photo 2 - FAA supplied view of the left main landing gear.



Photo 3 - FAA supplied view of a propeller blade.



Photo 4 - FAA supplied front quartering view of the left side of the airplane.



Photo 5 - FAA supplied view of a fuel sight glass.



Photo 6 - FAA supplied view of a propeller blade.



Photo 7 - FAA supplied front quartering view of the right side of the airplane.



Photo 8 - FAA supplied view of the right side of the airplane.




Photo 9 - FAA supplied view of a fuel sight glass.



Photo 10 - FAA supplied view of a tree and damage to the right wing leading edge.



Photo 11 - FAA supplied view of a tree and damage to the right wing leading edge.



Photo 12 - FAA supplied close-up view of a tree and damage to the right wing leading edge.



Photo 13 - FAA supplied view of the left elevator trailing edge.