



Memo for Record

**Craig Hatch
Air Safety Investigator
Central Region**

NTSB Accident Number: CEN19LA159, Textron Material Lab Report

Narrative: The following information was extracted from the Textron Material Report:

- The steel base assembly was separated at the swaged area that joins the threaded end piece
- Visual examination of the subject pressure switch showed heat damage to the base part of the switch
- The switch was cut open, and a visual examination showed no damage to the internal components
- There were no physical indications of how and why the two pieces broke loose at the swaged joint.