



Photo 1 – Accident Airplane

photo courtesy of R. Porter



Photo 2 – Engine Photo

courtesy of Continental Motors



Photo 3 - Oil Filter element



Photo 4 – Broken crankshaft is seen, behind connecting rod

Photo courtesy of Continental Motors



Photo 5 – Broken Crankshaft

Photo courtesy of Continental Motors




Photo 6 – Engine case half

Photo courtesy of Continental Motors