



Photo 1 – N6595J, a Piper PA-28D-180, at the accident site. (FAA photo).



Photo 2 - The cockpit. Note the fuel selector (red handle, bottom left) is positioned on the right fuel tank. (FAA photo).




Photo 3 – The engine was unremarkable. (FAA photo).



Photo 4 - Damage to the cowling after the nose gear separated. (FAA photo).



Photo 5 – Right wing damage. (FAA photo).



Photo 6 – Left wing damage. (FAA photo).