



Photo 1 – When N2XF made its forced landing, it went off the end of runway 7. Gouges in the ground were caused by the partially extended main landing gear. Irrigation pipe is at left and aircraft is in background



Photo 2 – N2XF rests in a clover field



Photo 3 – Close-up view of N2XF. Note the left rudder was knocked off when the airplane struck the irrigation pipe during its forced landing