



Photo 1 – N36PS at the accident site.



Photo 2 – Nose section and propeller.



Photo 3 – The engine.