




Photo 1 – View of damage to the engine mounts (Courtesy of FAA)




Photo 2 – View of damage to the engine mounts (Courtesy of FAA)