



Photo 1 – View of damage to the tail rotor drive system and the lower left side of fuselage (Courtesy of Operator)