



Photo 1 – View down runway 6's departure path. Pylons on runway mark muddy or soft spots



Photo 2 – N52794 at the accident site



Photo 3 – Left wing leading edge damage



Photo 4 – Left wing leading edge damage (another view)



Photo 5 – Right horizontal stabilizer, elevator, and rudder damage and skin wrinkling