



Photo 1 – Airplane at Accident Site



Photo 2 – Closeup of Deformation to Empennage