



Photo 1 – Supplied photo with a quartering view of the right, rear of the helicopter.



Photo 2 - Supplied photo with a quartering view of the left, front of the helicopter. The helicopter exhibits deformation in fuselage and tailboom skins.