



VIDEO SYNOPSIS
CEN20FA023

Jason Aguilera
Air Safety Investigator
Central Region

A local business provided closed circuit surveillance video that captured the impact sequence of N6678P. The video footage was reviewed at the business on December 2, 2019, and a download was provided by the business owner.

The provided video was in black and white, and faced generally south, viewing, mainly, the business's parking lot and areas across the street as well. The first indication of the accident airplane are the landing lights which illuminate the ground and spin in a counterclockwise circle. The lights make about one full rotation before the airplane enters the field of view. The airplane is viewed in about 70° nose low attitude. The camera views the cockpit side facing the camera as it rapidly descends. The airplane appeared to be in a left turning spiral as it impacted terrain and came to rest.

A still from the video is provided in the docket of this report.