



Photo 1 – View of main wreckage looking toward the northeast



Photo 2 – View of main wreckage looking toward the west



Photo 3 – View of propeller during post-scene examination



Photo 4 – View of crankshaft flange during post-scene examination



Photo 5 – Overall view of the wreckage during post-scene examination



Photo 6 – View of engine during post-scene examination