



Photo 1 – N257V at site viewed from its right rear (NTSB Photo)



Photo 2 – N257V at site viewed from its rear (NTSB Photo)



Photo 3 - N257V at site viewed from its left side (NTSB Photo)



Photo 4 - N257V at site viewed from its front (NTSB Photo)



Photo 5 – Accident site viewed from initial impact point (NTSB Photo)



Photo 6 – Airplane tail during postaccident examination (NTSB Photo)



Photo 7 - Airplane fuselage during postaccident examination (NTSB Photo)



Photo 8 - Airplane wings during postaccident examination (NTSB Photo)



Photo 9 - Airplane engine during postaccident examination (NTSB Photo)



Photo 10 - Airplane fuel pressure regulator during postaccident examination (NTSB Photo)



Photo 11 – Disassembled fuel pressure regulator (NTSB Photo)