



Photo 1 – Wreckage (FAA Photo)



Photo 2 – Empennage (FAA Photo)



Photo 3 – Aileron Rocker Shaft Connection (Pilot Photo)