



Photo 1 – Pre-accident photograph of N50JH in its hangar in Gross Ile, MI (family photo)



Photo 2 – Taxiway light struck by N50JH during takeoff, located at intersection of taxiways C and E (FAA photo)



Photo 3 – Aerial view of accident, located in residential neighborhood ½-mile south of ONZ (police department photo)



Photo 4 – Inverted N50JH. Note severed tree branches (FAA photo)



Photo 5 – The cockpit after airplane was righted (FAA photo)



Photo 6 – The pilot's seat (FAA photo)



Photo 7 – Missing control stick (FAA photo)



Photo 8 – Missing control stick socket (FAA photo)



Photo 9 – The instrument panel (FAA photo)



Photo 10 – The airspeed indicator, registering 72 mph (FAA photo)



Photo 11 – The tachometer, indicating 4,000 rpm (FAA photo)



Photo 12 – The Rotax engine. Note severed propeller blade (FAA photo)