

From: Mike Wells <[REDACTED]>
Sent: Tuesday, August 4, 2020 3:34 PM
To: 'Hatch Craig' <[REDACTED]>
Subject: RE: Piper PA020, Fuel exhaustion exam, NTSB, N4816A

Craig here is a short run down on my findings no useable fuel was found in the left tank.we drained the right tank and determined it had 5.5 gal of what appeared to be 100LL fuel.we checked the carb float bowl found fuel in the bowl, But no apparent water or dirt.reinstalled plug in bowl and refilled fuel drained from the right tank back in the right tank.removed mag p leads we did not have mag switch key. Primed the engine with primer an started and ran engine up to a high pwer setting.then Shut the engine down with the mixture.michael H. Wells A&P [REDACTED] if there are any other questions feel free to contact me.