

Hatch Craig

From: Hatch Craig
Sent: Tuesday, August 11, 2020 8:26 AM

Subject: Bell 206, N284S, Pilot's initial statement

Hi

Here's my transcription of a short video clip, that Deputy Colon had with the pilot just before being transported to the hospital.

About 5 minutes before refueling, helicopter was about 800 ft AGL, was in a slight left hand turn, with intention of landing on flat surface area, when he felt a slight vibration. Informed the crew of the emergency landing. The vibration was between the transmission and rotors and probably the rotors; the vibration intensified. [Hadn't felt something like this before] He was losing maneuverability, the vibration got extremely worst. They didn't make it to the intended landing area, before lost lift. The engine never stopped producing power;

Craig Hatch

(mailing address only)
4760 Oakland St. Suite 500
Denver, CO 80239

M-F 7:00 to 15:30 Central