



Photo 1 – Accident Airplane

Photo courtesy of McClung Aerial



Photo 2 – Removed cylinder with broken connecting rod



Photo 3 – Oil filter element



Photo 4 – View looking inside engine



Photo 5 – View looking inside engine



Photo 6 – Damaged connecting rod