



Photo 1 – Initial Tree Impacts (photograph provided by FAA)



Photo 2 – Initial Tree Impacts (photograph provided by FAA)



Photo 3 – Airframe Debris (photograph provided by FAA)



Photo 4 – Wreckage Debris Path (photograph provided by FAA)



Photo 5 – Main Wreckage (photograph provided by FAA)



Photo 6 – Engine and Propeller Assembly (photograph provided by Cirrus Aircraft)