



Photo 1 – Supplied view of the propeller in the debris field.



Photo 2 - Supplied view of the debris path through the woods.



Photo 3 - Supplied view of a separated control surface in the debris path.



Photo 4 - Supplied view of the engine at the accident site.



Photo 5 - Supplied view of the debris path through the woods.



Photo 6 - Supplied view of the debris path through the woods.



Photo 7 - Supplied view of the CAPS parachute in the debris field.



Photo 8 - Supplied view of the debris path through the woods.




Photo 9 - Supplied view of the compact flash exhibiting cracked NVM.



Photo 10 - Supplied view of the CAPS cover.