

Initial notification

- Pilot reported that he had been chasing a maintenance issue and had just replaced the exhaust.
- This was the first flight following that work.
- On departure and climbout, all cylinders went red and engine power was lost.
- During the forced landing to a field, the airplane sustained damage to the main gear and the right wing buckled per mechanic that was on board.