



Photo 1 – Accident Site



Photo 2 – Fuse Box (photo provided by Viking Aircraft Engines)



Photo 3 – Failed Fuse (photo provided by Viking Aircraft Engines)