



Photo 1 – N81624 at the accident site shortly after the forced landing



Photo 2 – N81624 being examined shortly after the forced landing



Photo 3 – Wrinkled fuselage fabric above right main landing gear



Photo 4 – Frontal view of fuselage damage and landing gear strut



Photo 5 – Rear view of fuselage damage and landing gear strut



Photo 6 – Dip sticking the fuel tank. The fuel tank was empty



Photo 7 – The cockpit of N81624. Notice hand-held communications radio and moving map display