



Photo 1 – Damage to Right Horizontal Stabilizer



Photo 2 – Damage to Emppenage



Photo 3 – Damage to Vertical Stabilizer