



Photo 1 – Exemplar Photo of the Accident Airplane

Date & Time: Wed, May 26, 2021, 13:41:01 CDT

Position: +032.450698° / -093.838693° (± 359.7 ft)

Altitude: 250ft (± 191.4 ft)

Datum: WGS-84

Azimuth/Bearing: 264° S84W 4693mils True ($\pm 17^\circ$)

Elevation Angle: -17.9°

Horizon Angle: $+00.3^\circ$

Zoom: 1.0X




Photo 2 – Airplane Wreckage

Date & Time: Wed, May 26, 2021, 14:05:29 CDT
Position: +032.450658° / -093.838545° (± 79.9 ft)
Altitude: 252ft (± 7.6 ft)
Datum: WGS-84
Azimuth/Bearing: 198° S18W 3520mils True ($\pm 19^\circ$)
Elevation Angle: -18.4°
Horizon Angle: $+00.2^\circ$
Zoom: 1.0X




Photo 3 – Airplane Wreckage, Front

Date & Time: Wed, May 26, 2021, 14:01:06 CDT
Position: +032.450673° / -093.838840° ($\pm 195.4\text{ft}$)
Altitude: 252ft ($\pm 71.2\text{ft}$)
Datum: WGS-84
Azimuth/Bearing: 056° N56E 0996mils True ($\pm 37^\circ$)
Elevation Angle: -17.6°
Horizon Angle: -01.0°
Zoom: 1.0X



Photo 4 – Airplane Wreckage, Right Side

Date & Time: Wed, May 26, 2021, 14:01:25 CDT
Position: +032.450549° / -093.838974° (± 462.2 ft)
Altitude: 253ft (± 160.3 ft)
Datum: WGS-84
Azimuth/Bearing: 085° N85E 1511mils True ([REDACTED])
Elevation Angle: -26.1°
Horizon Angle: -02.3°
Zoom: 1.0X



Photo 5 – Airplane Wreckage, Aft

Date & Time: Wed, May 26, 2021, 14:01:34 CDT
Position: +032.450430° / -093.838648° (± 192.2 ft)
Altitude: 252ft (± 87.8 ft)
Datum: WGS-84
Azimuth/Bearing: 117° S63E 2080mils True ($\pm 28^\circ$)
Elevation Angle: -18.8°
Horizon Angle: -00.0°
Zoom: 1.0X



Photo 6 – Airplane Wreckage, Left Side

Date & Time: Wed, May 26, 2021, 14:02:35 CDT
Position: +032.450582° / -093.838857° (± 29.8 ft)
Altitude: 243ft (± 11.7 ft)
Datum: WGS-84
Azimuth/Bearing: 150° S30E 2667mils True ($\pm 28^\circ$)
Elevation Angle: -31.5°
Horizon Angle: $+01.9^\circ$
Zoom: 1.0X



Photo 7 – Airplane Engine and Pylon



Photo 8 – Engine Inlet



Photo 9 – Engine Inlet and Compressor Disc