



Photo 1 – View of the separated propeller blade (courtesy of the Federal Aviation Administration).



Photo 2 – View of the damaged main landing gear and the underside of the fuselage (courtesy of the Federal Aviation Administration).



Photo 3 – View of the damaged left wing leading edge (courtesy of the Federal Aviation Administration).




Photo 4 – View of the damaged engine mount (courtesy of the Federal Aviation Administration).




Photo 5 – View of the deer caution notice in the terminal building at the Greene County – Lewis A. Jackson Regional Airport (I19) in Xenia, Ohio (courtesy of the I19 Airport Manager).