



Photo 1 – Main wreckage at accident site (Piper Photo)



Photo 2 – Main wreckage at accident site (Piper photo)



Photo 3 – Mufflers as found at accident site (Piper photo)



Photo 4 – Top view of engine at accident site (Piper photo)



Photo 5 – Accessory end of engine at accident site (Piper photo)



Photo 6 – Carburetor (Piper photo)



Photo 7 – Propeller (Piper photo)



Photo 8 – Propeller tree strike (Piper photo)