



Photo 1 – Vertical Stabilizer and Rudder Damage (Owner Photo)



Photo 2 – Left Wing Damage (Owner Photo)



Photo 3 – Throttle Body Injector Installed



Photo 4 – Throttle Body Injector