



Photo 1 – N686TM at the accident site. The departure end of runway 16, LXV, is at the top of the mesa in background (Robert Held photo)



Photo 2 – N686TM at the accident. Nose landing gear collapsed, left main landing gear strut pushed up through left wing, and right wing severed by tree (Robert Held photo)