



Photo 1 – View of the wreckage at the accident site (courtesy of Textron Aviation).



Photo 2 – View of the wreckage at the accident site (courtesy of Textron Aviation).



Photo 3 – View of the wreckage at the accident site (courtesy of Textron Aviation).



Photo 4 – View of the wreckage at the accident site (courtesy of Textron Aviation).



Photo 5 – View of the left horizontal stabilizer showing a wire strike (courtesy of Textron Aviation).



Photo 6 – View of the power lines at the accident site (courtesy of Textron Aviation).



Photo 7 – View of the airframe being laid out (courtesy of Textron Aviation).



Photo 8 – View of the left horizontal stabilizer showing the wire strike area (courtesy of Textron Aviation).



Photo 9 – View of the right propeller (courtesy Hartzell Propeller).



Photo 10 – View of the right engine (courtesy of Textron Aviation).



Photo 11 – View of the left propeller (courtesy of Hartzell Propeller).



Photo 12 – View of the left engine (courtesy of Textron Aviation).




Photo 13 – View of the fuel servo screens for the left engine and the right engine.



Photo 14 – View of the fuel servo screen for the left engine.