



Photo 1: Aircraft Damage to Left Wing and Left Wing Strut



Photo 2: Aircraft Damage to Empennage