



Photo 1 – Airplane At Accident Site (Photo from MKC Airfield Ops)



Photo 2 – Right Wing Damage (FAA Photo)