



Photo 1 - Aerial Photo of Accident Site (Ohio State Highway Patrol Photo)



Photo 2 - Main Wreckage, Front (Ohio State Highway Patrol Photo)



Photo 3 – Main Wreckage, Right (Ohio State Highway Patrol Photo)



Photo 4 – Aerial Photo of Main Wreckage (Ohio State Highway Patrol Photo)



Photo 5 - Propeller (Hartzell Propeller Photo)




Photo 6 - Airframe Propeller Pitch Control (PPC) Linkage Disconnected from PPC Splined Shaft
(Honeywell Aerospace Photo)