



RECORD OF CONVERSATION

Samantha Link
Aviation Accident Investigator
Central Region

Date: July 30, 2021
Person Contacted: Mr. Joseph Chavez (FAA Inspector)
NTSB Accident Number: CEN21LA241

Narrative:

During a telephone conversation with Mr. Chavez, he reported that the throttle cable from the cockpit appeared to be fractured near the throttle/choke assembly. The remaining portions of the throttle cable did not have any abnormal or abrupt bends, nor did it show indications of rubbing on other engine components. Mr. Chavez removed the throttle/choke assembly, along with the throttle and choke cables for shipment to the NTSB materials laboratory. He also shared the below photos:




Figure 1: Throttle/Choke Assembly




Figure 2: Close View of Throttle/Choke Assembly



Figure 3: Throttle Cable Fracture



Figure 4: Throttle Cable Splitter

END.

Submitted by: Samantha Link