



Photo 1 – Accident Location (Photo provided by local law enforcement)



Photo 2 – Left float hydraulic jack assembly (Photo provided by pilot/owner)