



RECORD OF CONVERSATION

Aaron M. Sauer
Senior Air Safety Investigator
Central Region

Date: 07/28/2021
Person Contacted: FAA Inspector Cull
RE: CEN21LA335

Narrative:

Inspector Cull reported the airplane sustained substantial damage to the engine firewall and engine mount (see photograph below). The inspector also noted a 4-port USB power supply adapter was plugged into a power port just below the flap switch.

