

Postaccident Photos
Courtesy of the Federal Aviation Administration

I. N747JG (RV-8)



Figure 1: Rudder Damage



Figure 2: Right Wing and Aileron Damage.

Postaccident Photos
Courtesy of the Federal Aviation Administration

II. N977RV



Figure 3: Aft Fuselage Damage



Figure 4: Left Wingtip

Postaccident Photos
Courtesy of the Federal Aviation Administration



Figure 5: Lower Left Wing Damage

END.

Submitted by: Samantha Link