

**CEN23FA080**

**INVESTIGATION PHOTOGRAPHS**



**Photograph 1 - Accident Site**



**Photograph 2 - Accident Site**



**Photograph 3 - Main Wreckage**



**Photograph 4 - Main Wreckage**



**Photograph 5 - Left Wing**



**Photograph 6 - Main Wreckage**



**Photograph 7 - Propeller Blades / Hub Fragments**



**Photograph 8 - Tree Limb at Accident Site**



**Photograph 9 - Engine**



**Photograph 10 - Engine / Propeller Flange**