



Photo 1 – View of the wreckage at the accident site (courtesy of Textron Aviation).



Photo 2 – View of the wreckage at the accident site (courtesy of Textron Aviation).



Photo 3 – View of the wreckage at the accident site (courtesy of Textron Aviation).



Photo 4 – View of the wreckage at the accident site (courtesy of Textron Aviation).



Photo 5 – View of the wreckage laid out at the salvage facility (courtesy of Textron Aviation).



Photo 6 – View of the wreckage laid out at the salvage facility (courtesy of Textron Aviation).



Photo 7 – View of the wreckage laid out at the salvage facility (courtesy of Textron Aviation).



Photo 8 – View of the engine at the salvage facility (courtesy of Textron Aviation).



Photo 9 – View of propeller blade A at the salvage facility (courtesy of Textron Aviation).



Photo 10 – View of propeller blade B at the salvage facility (courtesy of Textron Aviation).