

CEN22FA288

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter Wreckage at Accident Site (Courtesy of NTSB)




Photograph 2 - Separated Tail Rotor Section at Accident Site (Courtesy of NTSB)



Photograph 3 - Wire Wrapped Around Swashplate and Mast Fairing (Courtesy of NTSB)



Photograph 4 - Wire Wrapped Around Swashplate and Lower Mast Fairing (Courtesy of NTSB)



Photograph 6 - Wire Wrapped Around Leading Edge of Swashplate (Courtesy of NTSB)



Photograph 7 - Broken Pole and Wire (Courtesy of NTSB)



Photograph 8 - Closeup of Broken Pole and Wire (Courtesy of NTSB)